

Radiograph Troubleshooting

VARANIDEX INC.

1758 Tryon Rd Sharbot Lake ON K0H 2P0

JOEL READY
Equipment Service Technician

226.378.4532
London, Ont.

Ready Or Not
TECHNICAL SERVICES INC.

PARTIALLY EXPOSED RADIOGRAPHS

Possible causes:

- X-ray tubehead positioned incorrectly with respect to the imaging media
- Low developer fluid level, with resulting partial film development
- Two or more films placed against each other during development

CLOUDED RADIOGRAPHS

Possible causes:

- Outdated film (check expiry date)
- Film accidentally exposed to X-ray
- Film accidentally exposed to other natural or artificial light sources
- Improper development technique

RADIOGRAPHS SHOWING A BLACK LINE

This line appears when the film is excessively folded

RADIOGRAPHS SHOWING SIGNS OF ELECTROSTATIC ELECTRICITY

When a film is compressed too much and the air is dry, static electricity may occur, which displays black marks

RADIOGRAPHS WITH CHEMICAL SPOTS

Developer or fixer fluid spattered on the film before development and fixing procedures produces spots on the radiograph; such spots are:

- Dark, when caused by developer
- Light, when caused by fixer fluid

RADIOGRAPHS WITH EMULSION COMING OFF

If the film is kept in a hot water bath too long (e.g. throughout the whole night), or in the developer solution too long, the emulsion may become softer and partially come off the film base. After development, the film will show scratches

TYPICAL DEFECTS CAUSED BY INCORRECT POSITIONING

- Radiographs with elongated or shortened image:
The main beam is not perpendicular to the bisecting angle formed by the tooth longitudinal axis and the film
- Radiographs with stretched out tip of tooth
Probably caused by excessive film folding or bending inside the patient's mouth